## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	(wellbore fishing sensor process \$3).clm.	US-PGPUB	SAME	ON	2009/05/11 07:48
L2	4	(wellbore fishing sensor process \$3).clm.	US-PGPUB	AND	ON	2009/05/11 07:49
L3	0	(wellbore non- drilling sensor transmitter mud pulse).clm.	US-PGPUB	AND	ON	2009/05/11 07:51
L4	0	(wellbore non- drilling sensor mud pulse).clm.	US-PGPUB	AND	ON	2009/05/11 07:51
L5	1	(wellbore non- drilling sensor). clm.	US-PGPUB	AND	ON	2009/05/11 07:54
L6	0	(wellbore fishing non-drillilng). clm.	US-PGPUB	AND	ON	2009/05/11 07:56
L7	0	(wellbore threading non- drillilng).clm.	US-PGPUB	AND	ON	2009/05/11 07:57
L8	0	(wellbore unthreading non- drillilng).clm.	US-PGPUB	AND	ON	2009/05/11 07:57
L9	0	(wellbore tool non-drillilng). clm.	US-PGPUB	AND	ON	2009/05/11 07:57
L10	1	(wellbore tool non-drilling).clm.	US-PGPUB	AND	ON	2009/05/11 07:57

 $5/11/09\ 7:59:58\ AM$  C:\ Documents and Settings\ KThompson\ My Documents\ EAST\ Workspaces \ 10776089.wsp